


# ES 341

## 5 Step Speed Switch 9A

### Connection diagram:



### Technical data:

Supply: 230 V AC, 50 Hz  
Mains fuse: max. 10A  
Load: 9 A

### Description:

Stepped adjustment of motor speed of ventilators or heating elements.

The unit is equipped with a speed changer. 5 steps of speed and one off position.

Equipped with operation lamp which is illuminated in the 5 speed steps.

When the operation lamp is illuminated, the M1 terminal is live. This may be used for opening of a damper or a valve e.g. via an auxiliary relay. The unit is equipped with a built-in thermo switch reconnecting after cooling.

### Adjustment:

No adjustment is required.

### Mounting:

There are no requirements to cable length after the controller. Current regulations on cable dimensions must be observed.

Date: 07/04 -2000  
Drawn by: JEH  
Rev.: 1.2  
Manufactured by: LS Control A/S

**LSCONTROL**

www.lscontrol.dk tel. +45 5550 5550 fax +45 5550 2265